

Knowledge grows

4th April 2019

Our Reference: 200-200-LET-DWER-0004 Your Reference: MS870

Mr Ian Munro Manager, Compliance (Ministerial Statements) Department of Water and Environmental Regulation Prime House, 8 Davidson Terrace JOONDALUP WA 6027

Email: compliance@dwer.wa.gov.au

Dear lan,

Ministerial Statement No. 870, Condition 8 - Yara Pilbara Nitrates Groundwater Monitoring Results

In accordance with Condition 8-4 of Ministerial Statement 870, Yara Pilbara Nitrates (YPN) is required to conduct monitoring of all groundwater bores every six months. In the event that monitoring indicates an exceedance of trigger levels, Condition 8-5 requires that the results be reported to the CEO.

The most recent round of groundwater monitoring was conducted between the 19th and 21st of March, with results received on the 28th and 29th March 2019. As previously reported in 2017 and 2018, an elevation in levels of nitrogen species continues. Results of the March 2019 groundwater monitoring are provided below in Table 1, with exceedances of trigger levels highlighted.

Known unplanned releases have been previously reported to the Department of Water and Environmental Regulation (DWER) under Section 72 of the *Environmental Protection Act 1986* (31 March 2017,21 July 2017 and 22 September 2018) and the site was reported by Yara to DWER as a Known or Suspected Contaminated Site via submission of Form 1, on the 16th October 2018. On 7th December 2018 DWER classified the site as 'potentially contaminated – investigation required', and in this listing requested that a Contaminated Sites Auditor be engaged, and Detailed Site Investigation (DSI) be completed.

To date, YPN have taken the following actions in response to this issue:

Yara Pilbara Nitrates Pty Ltd

Postal Address Locked Bag 5009 Karratha WA 6714 Australia Visiting Address Lot 564 and 3017 Village Road Burrup WA 6714 Australia

Telephone +61 8 9183 4100 Facsimile +61 8 9185 6776 ABN 33127391422 Registered Office:

Level 5, 182 St George Terrace Perth WA 6000 Australia Telephone: +61 8 9327 8100 Facsimile: +61 8 9327 8199



- Completed a Tier 1 Risk Assessment, Tier 2 Risk Assessment and a Preliminary Hydrogeological Conceptual Site Model (in accordance with DWER guidelines) to assess environmental impact (submitted to DWER 19 June 2017 and 7 December 2017);
- 2. Undertaken an expanded groundwater monitoring program including the installation of an additional twenty seven site bores and three downstream bores;
- Commenced execution of an extensive repair project at the TAN Plant, with a focus on potential source mitigation in areas where groundwater contamination is known or likely;
- Engaged Golders to undertake further investigations (in accordance with DWER guidelines), including a Preliminary Ecological Risk Assessment (PERA), Preliminary Site Investigation (PSI) and DSI, which is currently being finalised; and
- 5. Engaged contaminated sites auditor, JBS&G.

| | | | MW1 | MW2 | MW3 | MW4 | MW5 |
|-----------------------------|-------|----------------|------------|------------|------------|------------|------------|
| | | | | | | | |
| Date | Units | Trigger Limits | 21/03/2019 | 19/03/2019 | 19/03/2019 | 19/03/2019 | 19/03/2019 |
| Aluminium (Filtered) | mg/L | 0.021 | 0.012 | < 0.005 | < 0.005 | <0.050 | <0.005 |
| Alkalinity (total) as CaCO3 | mg/L | 561 | 202 | 278 | 586 | 121 | 255 |
| Arsenic (Filtered) | mg/L | NA | <0.001 | <0.001 | <0.001 | <0.001 | <0.001 |
| Calcium (Filtered) | mg/L | 1,210 | 60.6 | 166 | 151 | 814 | 210 |
| Cadmium (Filtered) | mg/L | NA | <0.0001 | <0.0002 | <0.0005 | <0.0050 | 0.0013 |
| Chloride | mg/L | 95,700 | 269 | 1,910 | 8,380 | 78,500 | 5,060 |
| Chromium (III) (Filtered) | mg/L | NA | <0.005 | <0.005 | <0.005 | <0.010 | 0.009 |
| Chromium (VI) (Filtered) | mg/L | NA | <0.004 | <0.004 | < 0.004 | <0.004 | <0.004 |
| Copper (Filtered) | mg/L | NA | 0.0058 | 0.002 | 0.0007 | 0.04 | 0.0058 |
| Iron (Filtered) | mg/L | 0.26 | <0.005 | <0.005 | <0.005 | <0.050 | <0.005 |
| Mercury | mg/L | 0.0001 | <0.0001 | <0.0001 | <0.0001 | <0.0001 | <0.0001 |
| Magnesium (Filtered) | mg/L | 5,170 | 19.7 | 103 | 435 | 3,410 | 569 |
| Manganese (Filtered) | mg/L | 0.242 | 0.016 | 0.009 | 0.22 | 0.51 | 0.002 |
| Ammonium (NH4+) | mg/L | NA | <0.01 | 200 | <0.01 | 2.8 | 0.84 |
| Ammonia as N (NH3-N) | mg/L | 0.04 | <0.01 | 160 | <0.01 | 2.2 | 0.65 |
| Nitrate (as NO3) calculated | mg/L | 9.57 | 38.95 | 841.06 | 34.97 | 1,947.72 | 21,247.87 |
| Nitrogen (Total) | mg/L | 5.6 | 9.6 | 350 | 8.3 | 490 | 5,200 |
| Nickel (Filtered) | mg/L | NA | 0.003 | <0.002 | 0.01 | 0.057 | <0.010 |
| Oil and Grease | mg/L | NA | <10 | <10 | <10 | <10 | <10 |
| Lead (Filtered) | mg/L | NA | 0.0003 | <0.0002 | <0.0005 | <0.0050 | <0.0010 |
| TDS | mg/L | 143,000 | 830 | 4,200 | 15,000 | 140,000 | 38,000 |
| TSS | mg/L | 2,090 | 59 | <1 | 4 | 9 | 31 |
| Zinc (Filtered) | mg/L | 0.052 | 0.024 | 0.017 | 0.019 | 0.2 | 0.062 |
| pH (in-field) | | 6-8.4 | 7.38 | 6.77 | 7.15 | 7.01 | 7.15 |

Table 1: Six-Monthly Groundwater Monitoring Results



Please do not hesitate to contact the undersigned on 08 9183 4043 should you have any queries.

Yours Sincerely

Dr Ty Hibberd A/Health, Environment, Safety & Quality Manager Yara Pilbara Nitrates