



Yara Pilbara Nitrates Pty Ltd
Air Quality Monitoring Report
April 2022

13/05/2022 650-200-REP-YPN-0055 Rev 0

Ambient Air Concentration of Gases
NH₃, NO₂ and SO₂

Site	Date On	Date Off	NH ₃	NO ₂	SO ₂
			µg/m ³	µg/m ³	µg/m ³
Site 5 - Burrup Road	No new results received to date				
Site 6 - Water Tanks					
Site 7 – Hearsons Cove					

Notes:

- (1) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.
- (2) Samples contaminated due to being dropped



Yara Pilbara Nitrates Pty Ltd
Air Quality Monitoring Report
April 2022

13/05/2022 650-200-REP-YPN-0055 Rev 0

Airborne Particulate Concentration
Total Suspended Particulates (TSP)

Period Start Date ^{(1),(2)}	Site 5 (Burrup Road) TSP	Site 6 (Water Tanks) TSP	Site 7 (Hearsons Cove) TSP
	$\mu\text{g}/\text{m}^3$	$\mu\text{g}/\text{m}^3$	$\mu\text{g}/\text{m}^3$
06/03/2022	15	16	19
12/03/2022	12	14	13
18/03/2022	20	28	22
24/03/2022	22	22	25

Notes:

- (1) The date is the date that sampling commenced.
- (2) The Low Volume Air Sampler unit runs for a nominal 24 hours.
- (3) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd
Air Quality Monitoring Report
April 2022

13/05/2022 650-200-REP-YPN-0055 Rev 0

**Deposited Dust - Total Dust Deposition per Month
Insoluble and Soluble Fraction**

Site 5 - Burrup Road		Date Deployed	31/01/2022
		Date Collected	1/03/2022
Parameter	Unit	Limit of Reporting	
Soluble solids	g/m ² /month	0.7	1.9
Insoluble solids	g/m ² /month	0.8	1.3

Site 6 - Water Tanks		Date Deployed	31/01/2022
		Date Collected	1/03/2022
Parameter	Unit	Limit of Reporting	
Soluble solids	g/m ² /month	0.7	1.4
Insoluble solids	g/m ² /month	0.8	1.3

Site 7 - Hearsons Cove		Date Deployed	31/01/2022
		Date Collected	1/03/2022
Parameter	Unit	Limit of Reporting	
Soluble solids	g/m ² /month	0.7	1.7
Insoluble solids	g/m ² /month	0.8	1.3

Notes:

(1) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.