



Yara Pilbara Nitrates Pty Ltd
Air Quality Monitoring Report
June 2022

28/07/2022 650-200-REP-YPN-0057 Rev 0

Ambient Air Concentration of Gases
NH₃, NO₂ and SO₂

Site	Date On	Date Off	NH ₃	NO ₂	SO ₂
			µg/m ³	µg/m ³	µg/m ³
Site 5 - Burrup Road	No new results received to date				
Site 6 - Water Tanks					
Site 7 – Hearsons Cove					

Notes:

(1) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd
Air Quality Monitoring Report
June 2022

28/07/2022 650-200-REP-YPN-0057 Rev 0

Airborne Particulate Concentration
Total Suspended Particulates (TSP)

Period Start Date ^{(1),(2)}	Site 5 (Burrup Road) TSP	Site 6 (Water Tanks) TSP	Site 7 (Hearsons Cove) TSP
	$\mu\text{g}/\text{m}^3$	$\mu\text{g}/\text{m}^3$	$\mu\text{g}/\text{m}^3$
05-May-22	19	24	30
11-May-22	13	12	13
17-May-22	19	10	11
23-May-22	12	9	8

Notes:

- (1) The date is the date that sampling commenced.
- (2) The Low Volume Air Sampler unit runs for a nominal 24 hours.
- (3) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd
Air Quality Monitoring Report
June 2022

28/07/2022 650-200-REP-YPN-0057 Rev 0

**Deposited Dust - Total Dust Deposition per Month
Insoluble and Soluble Fraction**

Site 5 - Burrup Road		Date Deployed	31/03/2022
		Date Collected	29/04/2022
Parameter	Unit	Limit of Reporting	
Soluble solids	g/m ² /month	0.7	1.1
Insoluble solids	g/m ² /month	0.8	0.9

Site 6 - Water Tanks		Date Deployed	31/03/2022
		Date Collected	29/04/2022
Parameter	Unit	Limit of Reporting	
Soluble solids	g/m ² /month	0.7	1.6
Insoluble solids	g/m ² /month	0.8	0.8

Site 7 – Hearsons Cove		Date Deployed	31/03/2022
		Date Collected	29/04/2022
Parameter	Unit	Limit of Reporting	
Soluble solids	g/m ² /month	0.7	0.9
Insoluble solids	g/m ² /month	0.8	1.4

Notes:

(1) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.