



Yara Pilbara Nitrates Pty Ltd
Air Quality Monitoring Report
October 2022

21/11/2022 650-200-REP-YPN-0061 Rev 0

Ambient Air Concentration of Gases
NH₃, NO₂ and SO₂

Site	Date On	Date Off	NH ₃	NO ₂	SO ₂
			µg/m ³	µg/m ³	µg/m ³
Site 5 - Burrup Road	No new results received to date				
Site 6 - Water Tanks					
Site 7 – Hearson Cove					

Notes:

(1) Site 7 renamed from Deep Gorge to Hearson Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd
Air Quality Monitoring Report
October 2022

21/11/2022 650-200-REP-YPN-0061 Rev 0

Airborne Particulate Concentration
Total Suspended Particulates (TSP)

Period Start Date ^{(1),(2)}	Site 5 (Burrup Road) TSP	Site 6 (Water Tanks) TSP	Site 7 (Hearson Cove) TSP
	$\mu\text{g}/\text{m}^3$	$\mu\text{g}/\text{m}^3$	$\mu\text{g}/\text{m}^3$
02-Sep-22	17	20	21
08-Sep-22	15	16	18
14-Sep-22	19	20	18
20-Sep-22	17	17	12
26-Sep-22	24	24	20
02-Oct-22	20	21	17

Notes:

- (1) The date is the date that sampling commenced.
- (2) The Low Volume Air Sampler unit runs for a nominal 24 hours.
- (3) Site 7 renamed from Deep Gorge to Hearson Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd
Air Quality Monitoring Report
October 2022

21/11/2022 650-200-REP-YPN-0061 Rev 0

**Deposited Dust - Total Dust Deposition per Month
Insoluble and Soluble Fraction**

Site 5 - Burrup Road		Date Deployed	1/08/2022
		Date Collected	30/08/2022
Parameter	Unit	Limit of reporting	
Soluble solids	g/m ² /month	0.7	<0.7
Insoluble solids	g/m ² /month	0.8	0.9

Site 6 - Water Tanks		Date Deployed	1/08/2022
		Date Collected	30/08/2022
Parameter	Unit	Limit of reporting	
Soluble solids	g/m ² /month	0.7	1.8
Insoluble solids	g/m ² /month	0.8	<0.8

Site 7 – Hearson Cove		Date Deployed	1/08/2022
		Date Collected	30/08/2022
Parameter	Unit	Limit of reporting	
Soluble solids	g/m ² /month	0.7	1.2
Insoluble solids	g/m ² /month	0.8	<0.8

Notes:

(1) Site 7 renamed from Deep Gorge to Hearson Cove due to site relocation in April 2020.